

Date: Tuesday, 10/2/2007 10:41:45 AM
User: Kim Johnston

Process Sheet

44

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : LONG STEP ASSEMBLY HIGH SKID RH
Job Number : 34938	
Estimate Number : 10274	
P.O. Number : <i>N/A</i>	Part Number : D350591312
This Issue : 10/2/2007 S.O. No. : <i>N/A</i>	Drawing Number : D3272 REV B
Prsht Rev. : NC	Project Number : N/A
First Issue : <i>N/A</i> Type : LARGE FAB ASSY	Drawing Revision : B
Previous Run : 34797	Material : <i>N/A</i>
Written By : <i>[Signature]</i>	Due Date : 10/30/2007 Qty: 10 Um: Each
Checked & Approved By : <i>[Signature]</i> 07.10.02	
Comment : Est Rev: A 04.03.22 New issue KJ/RF Est Rev: B 07-06-09 Added D3572-1 JLM	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------



Comment: DOCUMENT CONTROL

Photocopy bluefile and type labels as per PPP D350-591-312 CHG001

10
KS 07.10.04
02/10/08

2.0	D32721	STEP
-----	--------	------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

STEP

BATCH: *B 35066*

10
07-10-24

3.0	D30671	End Plate
-----	--------	-----------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D3067-1 End Plate *B 34454*

10
07-10-24

4.0	D32191	Support
-----	--------	---------



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 D3219-1 Support *B 34453 = 13*
B 35080 = 7

10
07-10-24

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 10/2/2007 10:41:45 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 34938

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel end for welding FWD ONLY

2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod *M105058*
M105138

3-Grind End Plate flush

SAD

07-10-25

(10)

6.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

04/10/25

(10)

7.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

5 A/10/29

(10RH)

8.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

MS

07-11-29

(10RH)

9.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

07-10-31

10

10.0

D3065041

Step Leg Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number Description Batch
1 D3065-041 Step Leg Assy *333510*

07-10-31

10

11.0

D30661

Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick:

Qty Part Number Description Batch
2 D3066-1 Spacer *334447*

07-10-31

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 10/2/2007 10:41:45 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 34938

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

12.0

MS20600AD4W4

Rivets



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick:

Qty Part Number Description Batch

16 MS20600AD4W4 Rivet M105792

PE 07-10-31 10

13.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

Assemble Leg Assembly as per Dwg D3272.

PE 07-10-31 10

14.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

PE 07-10-31 (+10PH)

15.0

D30671

End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D3067-1 End Plate B34454

PE 07-10-31 10

16.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel Aft end for welding

2-Inspect for foreign object as per QSI 024

3-Weld Aft End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod M105058

4-Grind End Plate flush

5-Install last rivet.

PE 07-10-31 10
PE 07-10-31 10
PE 07-10-31 10
PE 07-10-31 10
PE 07-10-31 10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 10/2/2007 10:41:45 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 34938

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

17.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

07-10-31 (10)

18.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07/10/31 (10RH)

19.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Touch up Alodine

M-L 07/10/31

(10X)

20.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

M105914

M-L / BR 07/11/01

(10X)

21.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Wing Walk as per Dwg D3272 and QSI 005 4.4

FL 07/11/02 (10)

22.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: Inspect Powder Coat and Wing Walk

07/11/06 (10)

23.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

24.0

D22303

Mounting Lug



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 D2230-3 Mounting Lug

35013

7/11/06 SP

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 10/2/2007 10:41:45 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 34938

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

25.0

D2618

Bushing



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2618

Bushing

35096

59

26.0

D2856400

Abrasion Strip



Comment: Qty.: 0.6000 f(s)/Unit Total : 6.0000 f(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2856-400-720 Abrasion Strip

534293

59

27.0

D32351

Mounting Lug



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D3235-1

Mounting Lug

30996

56

28.0

D3278041

Support Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

1 D3278-041 Support Assembly

35287

50

7/11/07

29.0

AN335A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN3-35A

Bolt

M105408

50

30.0

AN413A

Bolt



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 AN4-13A

Bolt

M105653

62
M105906

2/11/05 56

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action - Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 10/2/2007 10:41:45 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 34938

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

31.0

AN536A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN5-36A

Bolt

M105906

SP

32.0

AN960JD10

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD10

Washer

M104625

SP

33.0

AN960JD416

Washer



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

16 AN960JD416

Washer

M105426

SP

34.0

AN960JD516

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD516

Washer

M104156

SP

35.0

MS21042L3

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L3

Nut (or -3)

M104625

7/11/05 SP

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: DD Date: 11/10/09
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Tuesday, 10/2/2007 10:41:45 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 34938

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

36.0

MS21042L4

Nut



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 MS21042L4

Nut (or -4)

M105054

SP

37.0

MS21042L5

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L5

Nut (or -5)

M104812

M105430

SP

(10x)

38.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

6 09/11/08 (410)

39.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D350-591-312

Location: B

16x
71.0k SP 87

40.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

(10)
09/11/09

Job Completion



U BT-11-09

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART

DESIGN <i>qp</i>	DRAWN BY <i>B</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>H</i>	DRAWING NO. D3272	REV. B SHEET 1 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE NTS
A	04.03.01	NEW ISSUE	
B	07.05.18	D3272-1 WAS D2622-120	

RELEASED07.06.04 *ff*

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	X	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.


SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. *34938*

Copyright © 2004 by DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN	90	DRAWN BY	90	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED	CE	APPROVED	CE	DRAWING NO. D3272
DATE	07.05.18	TITLE	STEP ASSEMBLY, HI LONG	SHEET 2 OF 3
		SCALE	1:20	REV.-B



D3272-041 STEP ASSEMBLY (LH. SHOWN)
D3272-042 STEP ASSEMBLY (RH, OPPOSITE)



THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


Copyright © 2004 by DART AEROSPACE LTD



DESIGN <i>GP</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE 1:20

RELEASED


07.06.04 *[Signature]*



DETAIL C

B D3272-1 STEP

(MAKE FROM D2622-120 STEP EXTRUSION)



DETAIL C
(SCALE 1:5)

DRILL $\phi 0.128$ (#30) FROM JIG ON
BOTH SIDES OF D3272-1 EXTRUSION
TO MATCH D3065-041 HOLE PATTERN

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 34938

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.